

SUPPLEMENTARY INFORMATION
Photos of Existing Site




Above: East Façade – Note Existing Mature Trees To Be Retained

Below: North Façade – Note Rooftop Equipment



SUPPLEMENTARY INFORMATION
Photos of Asphalt Parking Area



SUPPLEMENTARY INFORMATION
Photos Along Midway Road



Views Along Midway – North (L) and South (R)



View of Utility Generator – Lack of Landscaping and Screening Along Midway