

The two architects have expressed concern that if the irrigation system is not fixed in an expedient manner that we run the risk of doing further damage to the course. Staff believes replacing all damaged controllers on both courses at the same time is the best business decision. Regardless of the outcome of the Creek Course, any type of golf course or park area would require irrigation.

FINANCIAL IMPLICATIONS:

Professional Turf Products is the local representative for Toro and we are getting better than Buyboard pricing by using Eagle's corporate account. The actual quote is \$128,516.25 and staff added an approximate 5% contingency, for an amount not to exceed \$135,000.

STAFF RECOMMENDATION/ACTION DESIRED:

Staff recommends the City Council approve the purchase of irrigation supplies and labor from Professional Turf Products, LP, in an amount not to exceed amount \$135,000.